On The Record

Speed zone change being reviewed for Hwy. 101 N.

The City of Florence, along with Oregon Department of Transportation (ODOT), have submitted a speed zone review request within the Highway 101 corridor between Munsel Lake Road and the city limits.

Due to a number of citizen requests to ODOT, and with the city's concurrence, a speed zone review will take place as far north as Friendly Acres Road to Munsel Lake Road. Additionally, the City of Florence submitted a request for a speed zone review for the area between 31st along Highway 101.

While the speed review requests have been submitted, the actual investigation will take a number of months to complete. Typically, speed zone investigations are completed within 8-10 months after they the investigation is initiated.

The actual speed zone lowering the speed will im- prepared. The report is sent conducted by ODOT region traffic staff. The region traffic staff conducts an investigation using procedures in accordance with nationally standards.

Factors taken into consideration are crash history, roadside culture, traffic volumes and roadway alignment, width and surface.

The average daily traffic volume within this area is 9,900 to 11,500 vehicles per day (2017 data — the latest Street to the north city limits traffic volume data available). The traffic volume north of Munsel Lake Road is 9,900 vehicles per day and the volume increases as the roadway enters further into prior to the conclusion of the the city.

> Setting speed zones on Oregon's highways and streets is often a controversial issue.

street or in their community. On the other hand, speed zones that are unrealistic are often disregarded by a majority of motorists who are noraccepted traffic engineering mally careful and law-abiding drivers.

> A major factor in establishing speed zones is consideration of the 85th percentile or below which 85 percent of the vehicles are traveling. This is used as an indication of the speed most drivers feel is reasonable and safe.

> It is also important to point out that a request for a review of the speed limit does not mean there will be an imminent change to posted speeds review.

Once the investigation is complete, a report detailing the existing conditions and Many citizens believe that proposed changes (if any) is

investigation and review is prove traffic safety on their to the city for review. If the city agrees with the recommendation, the new speed zone is established.

Speed limits are set for ideal conditions. Drivers need to respond to adverse conditions. Oregon vehicle law requires that motorists drive at a reasonable and prudent speed and with a regard for speed. This is the speed at danger. Motorists must adjust their speed according to the existing vehicle and pedestrian traffic, road surface, lighting, and weather conditions.

> additional details For about how speed zones are established, call City of Florence Public Works at 541-997-4106.



BAY STREET GRILLE

CLAWSON'S WHEELHOUSE* (*RHODY WEEKEND ONLY)

> THE HUKILAU THE FIREHOUSE

ICM RESTAURANT

TRAVELER'S COVE **BUTTONS AVAILABLE AT LOCAL MERCHANT**

Find us on Facebook BUTTON! FACEBOOK.COM/SIUSLAWNEWS



877-374-8377 | THREERIVERSCASINO.COM

POLICE

March 24

- Accident, with unknown injury, was reported on the 89100 block of Spindrift Way.
- Escape was reported on the first block of Redwood Street.

March 25

• Accident, without injury, was reported on the first block of Highway 101.

- March 26 • Theft was reported on
- Hit-and-run accident was reported on the 200 block of Laurel Street.

the 1900 block of 30th St.

•Arrest, with warrant, was reported on the 1200 block of Bay Street.

March 27

- Arrest, with warrant, was reported on the first
- block of Kingwood Street. • Hit-and-run was reported on the 1600 block of 12th
- Street. • Trespass was report-
- ed on the 85500 block of Glenada Road.

March 28

- Arrest, with warrant, was reported on the 1600 block of Highway 126.
- Trespass was reported on the 2200 block of 16th St.
- Assault was reported on the 87500 block of Rice Road.

March 29

- Theft was reported on the 900 block of Highway
 - Theft was reported on

the 4700 block of Highway


• Arrest, with warrant, was reported on the 400 block of Ninth Street.

March 30


- Theft was reported on
- the 300 block of Ninth St. · Accident, without injury, was reported on the 400
- block of Highway 101. • Arrest, with warrant, was
- reported on Ninth Street.
- Arrest, with warrant, was reported on Spruce Street.
- Shots fired was reported on the 83700 block of Highway 101.

March 31

· Trespass was reported on the 800 block of Highway



Visit florencefestoregon.com for information or call 541-997-9136



541-997-1040 • pacificpub@gmail.com