



# AVALANCHE SCENES, NEAR WELLINGTON, WASH.


PHOTOGRAPHS SHOW STRIKINGLY THE TREMENDOUS DAMAGE WROUGHT BY SLIDE, WHICH COST LIVES.




PLACE WHERE THE TRAIN STOOD WHEN THE AVALANCHE STRUCK IT.



DIGGING BODIES OUT OF WRECKAGE. - STEAM PIPES TWISTED AROUND STUMP.



RESCUE PARTY HAULING RECOVERED BODY TO SCENIC HOT SPRINGS.




ONE OF THE GREAT NORTHERN CARS CRUSHED LIKE AN EGG SHELL IN THE WELLINGTON SLIDE.



ONE OF THE MAIL CARS IS BURIED UNDER THIS MASS OF SNOW AND TANGLE OF LOGS.



TWO 150-TON LOCOMOTIVES, GIVING MUTE EVIDENCE OF AWFUL POWER OF SNOW SLIDE.



HUNTING FOR BODIES IN THE WRECKAGE.